Mar. 11 2010 03:59PM P3

PHDNE NO. : 8703386376

FROM : ROSIE SWAN

Clay,

This is my report for the week (2/22/10 thru 2/28/10).

Equal pond to the Bio pond: 45.0 hours Bio pond to the Equal pond: 45.0 hours

Sumps & tank dikes to the Equal pond: 20.0 hours

Stormwater pond to the Polish pond: 6.0 hours(1 pump)

I worked 8 hours on paperwork, sampling, and pump service. I worked a total of 53 hours, but reported only 40 hours.

Gary, Cedar Chemical Plant